

RECEIVED

MAR 26 2001

DIVISION OF
OIL, GAS AND MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 5/00 To (mo./yr.) 3-01
2. DOGM File Number (Mine No): 52/300/68 5/23/068
3. Mine Name: DESERT MINE
4. Mineral(s) Mined (or permitted to mine): PRECIOUS METALS
5. Type of mine ☐ Surface Mine or ☒ Underground Mine
6. Legal Description (Location of Lands Affected):
NW 1/4, NW 1/4, NW 1/4, Section 28, Township 12S, Range 7W
SW 1/4, SW 1/4, SW 1/4, Section 21, Township 12S, Range 7W
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: DAVID J HANSEN - TIM J CARSON
8. Permanent Street Address: 129 EAGLE ST P.O. Box 378
City, State, Zip: EUREKA UT 84628
Phone: 435-433-1019 Fax: _____
9. Company Representative (or designated operator):
Name: DAVID J HANSEN / TIM J CARSON
Title: OPERATORS PARTNERSHIP
Business Address: P.O. Box 378
City, State, Zip: EUREKA UT, 84628
Phone: 435-433-1019 Fax: _____
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☐ No ☒
2. If no - what was the last year of activity? 1999 ✓
3. If yes - how much ore or mineral was mined? N/A

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
DUE TO SUBSTANCIAL DAMAGE TO HOIST AND
SHAFT FROM VANDALS, NO UNDERGROUND MINING
WAS PERFORMED. SAMPLING OF MINE DUMPS
WAS DONE, WITH NO NEW SURFACE DISTURBANCE
5. How much **additional acreage** was disturbed during the past year? NONE
6. How much acreage was **reclaimed** during the past year? NONE
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
NO RECLAMATION WAS PERFORMED DUE
TO DELAY OF MINING OPERATIONS
8. What is the **total** disturbed acreage of entire project at years end? 0
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.
TO BE DETERMINED WHEN MINE IS
IN SAFE OPERATIONS AGAIN.
AS PER MSHA REGULATIONS.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

DAVID J HANSEN

Title of Operator:

SENIOR OPERATOR

Signature of Operator:

David Hansen

Date:

3-23-01